


# JIFFY® LECTRIC™ STX PRO ICE DRILL – PARTS LIST

Includes D-Ice'r ARMOR™ Drill Assembly



Ref. No.	Part No.	Description	No. Used
1	3909	Cover	1
2	3965	"L" Handle	1
3	3810	Motor	1
4	3961	Switch	1
5	3968	"U" Handle	1
6	3949	Throttle Assembly	1
7	3954	Throttle Wire	1
8	2512	Push Nut	2
9	3946	Handle Plate	1
10	3921	Motor Mount Plate	1
11	3915	Jumper Wire	1
12	2355	Hex Capscrew	2
13	2336	Lock Nut	7
14	3811	Wiring Harness	1
15	4036	Pinion Gear Assembly	1
16	3843	Flat Washer	1
17	3720	Upper Gear Housing	1
18	3707	Main Gear & Shaft Assy.	1
19	3721	Lower Gear Housing	1
20	1689	Flat Washer	15
21	3983	Lock Washer	4
22	1683	Hex Capscrew	5
23	1119	Lock Washer	1
25	3228	Hex Capscrew	1
26	1670	Flat Washer	1
27	3634	Teflon™ Washer	1
28	3972	Clevis Pin	1
29	3971	E-Z Connect™	1
30	3730-PRO	6" STX PRO Drill Assy.	1
"	3731-PRO	8" STX PRO Drill Assy.	1
31	3301	6" Blade Protector	1
"	4038	8" Blade Protector	1
32	3586-STX	6" Stealth STX Blade Kit	1
"	3588-STX	8" Stealth STX Blade Kit	1
33	3917	96" Cable Assembly	1



tesstools.net  
800 397 7553