


WIRING DIAGRAM

Scale document up



MODEL 6012 PARTS LIST

Item	Description	Part No.
1	Front leg	610825
2	Wheels w/nuts	605672
3	Axle w/nuts	610052
4	Transformer	610819
5	Rectifier	610364
6	Fan Blade	610189
7	Fan Motor	610190
8	Timer	611245
9	Ammeter	605204
10	DC Circuit Breaker	610536
11	DC Cable set	610820
12	Base	610054
13	AC Cord	611248
14	Switch w/knob	611187
15	Clamps (1pair, includes jaws)	6202
16	Jaw Kit (repairs 1 clamp)	610970
17	Front Panel	611251
18	Right Side Panel	611032
19	Back Panel	610977
20	Pointer Knob-Switch	603147
21	AC Circuit Breaker	603597
22	Handle	605213
Not shown		
	Top Panel	611011
	Left Side Panel	611031

